

TOP SECRET

PRIORITY

IN 02486

PRITY [] CITE [] ZERO TWO FOUR ONE

25X1

[] ZERO FOUR SLANT ONE TWO THREE ZERO ZULU

25X1

REF [] TWO NINE NINE SIX

25X1

MISSION TWO ZERO ZERO NINE. PRIMARY CAMERAS MALFUNCTIONED AFTER TWO ZERO MINUTES OF OPERATION DUE TO FAILURE OF IMC RPT IMC MOTOR. DRIVE SHAFT OR ARMATURE WAS FROZEN. TRACKER FILM OPERATED FOR ALFA TOTAL OF SIX HOURS. OPERATION WAS SATISFACTORY. APPROXIMATELY SIX FIVE ZERO FEET OF SEVEN ZERO MIKE MIKE WAS EXPOSED. MISSION TWO ZERO ONE ZERO. POST FLIGHT INSPECTION REVEALED RIGHT OBLIQUE CAMERA MALFUNCTIONED DUE TO BROKEN SHUTTER SPRING. CAUSE DETERMINED AS METAL FATIGUE. TRACKER WORKED SATISFACTORY EXPOSING SIX ZERO ZERO FEET OF SEVEN ZERO MIKE MIKE FILM.

1

TOP SECRET